

	National Aeronautical Laboratory	Documentation Sheet	Document Classification Restricted
Title	: Investigation of Damaged Components of MIG-21 Type-96 Aircraft No. C-1665	Document No.	PD MT 8658
Author(s)	: A.C.Raghuram, S.Radhakrishnan, R.V.Krishnan & V.Ramachandran	Contents	2 pages, incl. 1 figure
Division	: Materials Science	No. of copies:	12
External participation	:	NAL Project No.	MT-9-861, MT-1-167
Sponsor	: Aeronautics R & D Board	Sponsor's Project No.	Aero/RD-134/100/10/
Approval	: A.C.Raghuram	84-85/394	
Remarks	:	26	
Keywords	: Canopy, Soot deposit, Aileron, Overload fracture, Accumulator, Impact damage, Blueing		
Abstract	:		

A MIG-21 aircraft was involved in an accident. The report records the observations and comments on a few components retrieved from the wreckage.